

# HelicopterBuyer, Inc.

1989 Bell 206 L3

S/N: 51328

2,473 hours TT

## Maintenance Tracking Data Summary

Airframe	Part Number	O/H	T/R	% T/R		Airframe	Part Number	Life	T/R	% T/R
M/R Hub Assy	206-011-100-151	2,400	2,300	96%		M/R Blade	206-015-001-107	3,600	1,126	31%
Swashplate & Support Assy	206-010-450-117	4,800	2,326	48%		M/R Blade	206-015-001-107	3,600	1,126	31%
Mast Assembly	206-040-014-103	3,000	526	18%		M/R Mast	206-040-535-109	5,000	2,526	51%
Transmission	206-040-004-107	4,500	2,026	45%		M/R Mast - CY	206-040-535-109	44,000	35,620	81%
Freewheel Assy	206-040-270-009	3,000	526	18%		M/R Trunnion - CY	206-011-120-103	24,000	23,641	99%
Freewheel "Sprag" Clutch	CL42250-1	3,000	526	18%		M/R Ret Strap Fitting	206-011-150-105	2,400	2,300	96%
Tail Rotor G/B	206-040-402-003	6,000	3,526	59%		M/R Ret Strap Fitting	206-011-150-105	2,400	2,300	96%
Tail Rotor Hub	206-011-810-139	2,500	1,630	65%		Ret Strap (Due 6/09)	206-011-154-107	1,200	1,100	92%
Hyd Servo #1 - LH	206-076-062-003	3,600	1,126	31%		Ret Strap (Due 6/09)	206-011-154-107	1,200	1,100	92%
Hyd Servo #2 - RH - Cyclic	206-072-062-003	3,600	1,126	31%		M/R Ret Strap Pin	206-011-125-001	1,200	952	79%
Hyd Servo #3 - Collective	206-076-062-003	3,600	1,126	31%		M/R Ret Strap Pin	206-011-125-001	1,200	952	79%
						M/R Ret Strap Bolt	206-011-260-101	1,200	982	82%
						M/R Ret Strap Bolt	206-011-260-101	2,400	982	41%
<b>250-C30P Engine</b>	<b>Part Number</b>					M/R Grip	206-011-132-113A	4,800	2,326	48%
<b>S/N: CAE 895391</b>						M/R Grip	206-011-132-113A	4,800	2,326	48%
<b>2,473hrs / 4154 Cycles</b>	<b>23004545</b>	<b>O/H</b>	<b>T/R</b>	<b>% T/R</b>		R/H Cyclic Tube	206-001-193-001	4,800	2,326	48%
Impeller - RT	23030976	12,500	10,026	80%		L/H Cyclic Tube	206-001-193-001	4,800	2,326	48%
Impeller - RT - CY	23030976	25,000	TBD	TBD		S/P Support	206-010-445-105	4,800	2,326	48%
#1 Turbine - RT	23053299	2,025	1,206	60%		S/P Col Sleeve	206-010-454-109	4,800	2,326	48%
#1 Turbine - Cycles	23053299	3,000	1,725	58%		Collective Lever	206-010-467-001	4,800	2,326	48%
#2 Turbine - RT	23032280	2,025	1,206	60%		Collective Idler Link	206-010-407-001	4,800	2,326	48%
#2 Turbine - RT - CY	23032280	3,000	1,725	58%		Tail Rotor Yoke	206-011-819-105	5,000	1,635	33%
#3 Turbine - RT	6898663	4,550	2,076	46%		Tail Rotor Blade	206-016-201-131	2,500	1,630	65%
#3 Turbine - RT - CY	6898663	6,000	1,846	31%		Tail Rotor Blade	206-016-201-131	2,500	1,630	65%
#4 Turbine - RT	6892764	4,550	2,076	46%		T/R Duplex Bearing	206-040-410-005	3,000	526	18%
#4 Turbine - RT - CY	6892764	6,000	1,846	31%						
Tie Bolt	23008030	9,000	TBD	TBD						
Fuel Control (f/mod status)	23065147	1,500	518	35%						
Fuel Pump	6896822	3,000	526	18%		<b>Average Weighted Component Time Remaining</b>				<b>64%</b>
Fuel Nozzle	23077067	2,000	1,315	66%						
Bleed Valve	23005366	1,500	518	35%						
Governor	23065125	2,000	1,524	76%						