

Helicopters - Engines Brokerage - Sales - Acquisitions.

Honeywell T5317A-1 Engine Exclusively Offered For Sale

S/N: LE-07648C 4,976 hours Total Time



Representative Photo



Fresh 1,250 Hour Hot Section Inspection by Honeywell Service Center

- All gears and bearings inspected
- All New Seals
- Compressor Inspection
- New Air Diffuser
- Fresh Paint
- Converted to T5317 Per Honeywell Engine Fabrication Instructions (EFI)

Recent Engine Overhaul – 292 Hours TSO by Honeywell Authorized Service Center

- 91% Component Value Remaining
- All AD's and SB's Compliant
- 2 Year / 1,000 Hours Engine Warranty
- Power-By-The-Hour Program Available
- Run-Out T53 Exchange / Upgrade / Outright

For Additional Information Contact:

Mark V. Clancy Phone: +1-763-218-2000

E-Mail: Mark@HelicopterBuyer.com